

GREGORY S. BELL

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Reviewed My

Minerals Inspection Report

Report Date:

Mine Name: United Stone		Permit Number:	S470079	Mine Status:	Forfeiture
Operator Name: United Stone and Design		Inspection Date:	05212014	Permit Fees:	No Fee Req.
Inspe	ector(s): A. Abate	Inspection Time:	0900 AM	Bond Amount:	\$3,900
Atter	ndee(s): A. Jiron	Weather:	Clear	Bond Escalation:	
Inspe	ection Purpose: Check on the status of the clean up	activity at all stone sites		Prior Inspection:	05/06/2009
Site v	clusions and Recommendations work is being completed by Mr. Ab Jiron, a local st ng the former United Stone sites cleaned up. Availa ts, or for additional seed mix.	able funds could be put towa	rd either compen	sating Mr. Jiron for the r	reclamation
	Elements of Inspection			valuated & Commented	Enforcemen
1.	Permits, Revisions, Transfer, Bonds				
	The bond was forfeited a few years back. Several	sites are in the process of be	ing cleaned up b	y another stone dealer.	
2.	Public Safety (shafts, adits, trash, signs, highwalls)				
3.	Protection of Drainages/Erosion Control				
4.	Deleterious Material				
	Materials consisted mainly of rock and some steel operator is making excellent progress on cleaning when compared to photos of the same sites in prev comparison to what has already been accomplished	up all these areas. Overall, vious years. Work still remain	very little stone a	and debris were present o	n these sites
5.	Roads (maintenance, surfacing, dust control, safet	y)			
6.	Reclamation				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)				
8.	Soils				
9.	Revegetation			\boxtimes	
	Noticable vegetation was growing back in disturbing funds, seeding does not appear to be appriority.	ance areas. Site appears to b	e revegetating its	self. Given the low amou	ınt of available
10.	Other	1			
Insp	ector's Signature:	1			

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M047-Uintah/S0470079-UnitedStone/inspections/Insp-05212014.pdf



Mine: S470079 Inspected: 05212014



Site 1: Stone is being cleaned up. New vegetation growth is present. According to Ab, the clean up here was the worst site of all.



Site 1: Small piles are all that remain. Ab is actively cleaning this rock up and palletizing it for shipment.



Site 2: Reported barrels and trash at this site are cleaned up. Flat staging area will remain for the gas company.




Site 4: Former camp area. Trash and tents have been cleaned up. Ab will reclaim the road from here to Site 5.



Mine: S470079 Inspected: 05212014




Site 5: The ledges still had some debris in the area. Stone was being organized into piles.



United Mess: This was the worst of the sites I saw. The plan is to reclaim in June 2014.



Stone was laying on the ground naturally in some areas such as this.



An example of the steel bins on some of the sites.



Inspected: 05212014



Site 7: Photo of the grading work



Site 8: Panoramic (photos L and R) Vegetation is beginning to grow.





Inspected: 05212014



